


### Additional Data/Spec Sheet

#### LP Brass Adapter Fittings – NPT Male x NPT Female Adapter

## 222P Adapter



| Part Number | Pipe Thread 1 | Pipe Thread 2 |
|-------------|---------------|---------------|
| 222P-2-2    | 1/8           | 1/8           |
| 222P-4-2    | 1/4           | 1/8           |
| 222P-4-4    | 1/4           | 1/4           |
| 222P-6-2    | 3/8           | 1/8           |
| 222P-6-4    | 3/8           | 1/4           |
| 222P-6-6    | 3/8           | 3/8           |
| 222P-8-4    | 1/2           | 1/4           |
| 222P-8-6    | 1/2           | 3/8           |
| 222P-8-8    | 1/2           | 1/2           |
| 222P-12-6   | 3/4           | 3/8           |
| 222P-12-8   | 3/4           | 1/2           |
| 222P-12-12  | 3/4           | 3/4           |



## Adapter 222P

| PART NO.   | 1 PIPE THREAD | 2 PIPE THREAD | C HEX  | L    | FLOW DIA. D |
|------------|---------------|---------------|--------|------|-------------|
| 222P-2-2   | 1/8           | 1/8           | 9/16   | .88  | .220        |
| 222P-4-2   | 1/4           | 1/8           | 3/4    | 1.06 | .220        |
| 222P-4-4   | 1/4           | 1/4           | 3/4    | 1.25 | .314        |
| 222P-6-2   | 3/8           | 1/8           | 7/8    | 1.10 | .220        |
| 222P-6-4   | 3/8           | 1/4           | 7/8    | 1.25 | .314        |
| 222P-6-6   | 3/8           | 3/8           | 7/8    | 1.25 | .440        |
| 222P-8-4   | 1/2           | 1/4           | 1      | 1.47 | .314        |
| 222P-8-6   | 1/2           | 3/8           | 1-1/16 | 1.47 | .440        |
| 222P-8-8   | 1/2           | 1/2           | 1-1/16 | 1.66 | .564        |
| 222P-12-6  | 3/4           | 3/8           | 1-3/8  | 1.50 | .440        |
| 222P-12-8  | 3/4           | 1/2           | 1-3/8  | 1.69 | .564        |
| 222P-12-12 | 3/4           | 3/4           | 1-3/8  | 1.69 | .752        |

## Assembly Instructions

### Straight Fittings

1. Hand tighten external thread into internal thread
2. Tighten an additional 2 turns with a wrench up to 1/2" male pipe thread.
3. Above 1/2" 1 1/2 to 2 1/2 turns.

